


External dimensions depend on the type of the servo motor. Indicated dimensions are in case of FANUC. Please contact us for CAD files (2D:DXF, 3D:PARASOLID).

CNC1000,1200




R
RIGHT HAND


WITH
FACE
PLATE

AR21
CTRL

★ Exclusively for Horizontal models.




CNC1201 PAT.



R
RIGHT HAND


WITH
FACE
PLATE

AR21
CTRL



★ Please contact us about the back support for vertical use.


CNC1600 PAT.



R
RIGHT HAND

WITH
FACE
PLATE


AR21
CTRL





★ Please contact us about the back support for vertical use.

Application of the Large Rotary Table

Machining of the gears with large module



Hobbing of the gears with large module



Configuration of the large rotary table on the horizontal M/C to machine a propeller hub of the windmill.