



# CNC ROTARY TABLE with AR21 CONTROLLER



## CNC105AR21-04



Powerful Clamping Torque : 205Nm




Air purge function is provided.


## CNC180AR21-04



CNC180AR21-04 (400W) is standard. CNC180AR21-08 (750W) and CNC180AR21-06 (High Torque) are available.




Powerful Clamping Torque : 303Nm




Air purge function is provided.


## CNC202AR21-08



CNC202AR21-08 (750W) is standard. CNC202AR21-06 (High Torque) is available.



Powerful Clamping Torque : 303Nm




Air purge function is provided.


## CNC205AR21-05



CNC205AR21-05 (450W) is standard. ★Built-in type rotary joint 6+1 can be mounted.




Powerful Clamping Torque : 380Nm




Air purge function is provided.

Rotary joint shown in photo is optional.

## NCT200AR21-08



Powerful Clamping Torque : 900Nm




Air purge function is provided.

## CNC260AR21-08, 302AR21-08


CNC260, 302AR21-08 (750W) is standard. CNC260, 302AR21-06 (High Torque) is available.



CNC260



Pneumatic Clamping Torque UP 588Nm



For the rotary table with pneumatic brake, air purge function is provided inside the motor cover as standard.

High speed rotation Z series is available for all models of CNC rotary table. e.g. CNCZ260AR21